

Design of 5 K. W.-1,000 Ampere-110/5
Volt High Current Transformer

E. J. Wickersham
W. F. Parker
J. F. Kadic
A. W. Tyler

1905

537.832
W 63

ARMOUR
INST. OF TECH. LIB.
CHICAGO.



**Illinois Institute
of Technology
Libraries**

AT 24

Wickersham, E. J.

Design and construction of 5

k.w. - 1,000 ampere- 110/5

432
117 a

DESIGN AND CONSTRUCTION OF
5 K. W. - 1,000 AMPERE - 110/5 VOLT HIGH CURRENT TRANSFORMER.

A Thesis presented by

E. J. Mickuschau.

W. H. Parker

J. F. Radic

W. Tyler

to the
President and Faculty
of the

ILLINOIS INSTITUTE OF TECHNOLOGY
PAUL V. GALVIN LIBRARY
35 WEST 33RD STREET
CHICAGO, IL 60616

Armour Institute of Technology

for the Degree of

Bachelor of Science in Electrical Engineering

Having completed the prescribed course of study in
Electrical Engineering.

C. E. Freeman

Per Snow.

Chicago, June 16th, 1905.

H. M. Raymond.

Dean of Engineering Studies,

L. C. Morin

Dean of Cultural Studies.

In the calibration of higher reading ammeters it is necessary, on account of the high current required, to use too large an amount of power to be economical when the current is supplied at the normal voltage of an ordinary A. C. generator. For this reason it is advisable to use a transformer in connection with the generator, which lowers the voltage and gives a higher current, and only changes the power by an amount equal to the losses in said transformer.

The ordinary transformers built and such as are in the laboratories of technical institutions are built for transformations of about 1,000 to 100, or possibly from 1,000 to 50 volts. A generator, to supply current for calibration purposes, should not be larger than 4 or 5 K. W. at the most, to be economical. With this, the above transformer of 1,000/100 volts would then give a current of 50 amperes at 100 volts. Then to obtain the higher current readings requires another transformer in connection with this one. This second transformer would have to be specially designed on account of the high current at its secondary.

The transformer which we think best suited for this purpose and the design of which we have chosen for our thesis, is one to transform from 110 (pri.) to 5 volts (sec). The capacity to be such (5 K. W.) that a current of 1,000 amperes may be delivered at the secondary. This will easily encompass the entire scale of the majority of the ammeters in use in any technical institution and in the various commercial uses to



which ammeters are put; as the higher reading ammeters (5,000 amperes, etc.) of course only take a shunted current and do not take a current higher than 1,000 amperes.

There is another field in which the above transformer may be used; that is, in electro-chemistry. We know that the heat developed in any circuit is represented by $I^2 R$ -- I being the current in amperes flowing in the circuit, and R the resistance in ohms of the circuit. From this we can see that to obtain the maximum amount of heat with the least expenditure of power, we must have the highest current with the lowest voltage feasible, as the power is expressed by $E I$ -- where E is the voltage across the circuit. From this discussion it may readily be seen that the above transformer will also be valuable in the electric furnace, where currents as high as 1,000 amperes are required to give the necessary heat.

In designing a transformer certain conditions are imposed under which it is to operate, as the primary and secondary voltages, capacity, frequency of alternation and minimum allowable efficiency.

There are three methods of design which are as follows:

- I. Analytical Method;
- II. Trial and Error Method;
- III. Empirical Method.

However if the given conditions call for a design that **departs** considerably from previous experience, the second method is the only one available. This consists in assuming various values for B, dimensions and shape of core, current density and number of turns of wire and selecting the transformer best suited to the given conditions.

The first thing to be done in the design of a transformer is to decide upon the type and the method of cooling. We decided that the core type was the best suited to our conditions, as it would be difficult to wind such heavy wire as we would necessarily have to use for high currents, on a shell type of transformer. In regard to cooling, air cooling will give very satisfactory results when using a core type of transformer of this size.

We will now consider the general equation for a transformer, which is:-

$$E \approx \frac{4.44 \pi N_p A B f}{10^8} \text{ volts, in which}$$



E = Counter, E. M. F.

N_p = No. turns on primary,

A = Area cross section of core sq. in.,

B = Flux density (lines / \square "),

f = Frequency.

The next thing to consider is, the conditions imposed upon the transformer; they are:-


Capacity 5 K. W.

Secondary current 1,000 amperes,

Primary voltage 110,

Frequency 60 cycles.

From this we can see that the only variables in the above equation are N_p , A and B. But for any value of A, B is a constant; this then narrows it down to N_p and either A. or B as the variables. As we desire to construct the transformer



with the laminated core as shown in the accompanying sketch, it is advisable to assume a certain inside diameter of coil and from this calculate the values of A and B resulting; leaving the spaces m , m for air circulation to aid in cooling.

One other variable that does not come directly into the above equation is the current density in the coils, This then leaves us with three variables to consider -- the number of turns on the primary, the diameter of core, and the density of current in coils.

We carried out a series of calculations with various

values of these variables, obtaining all data of the transformer and its efficiency under all the various conditions which we assumed. We limited the flux density in the core to 40,000 lines per sq. in. which seemed to be a maximum upper limit consistent with good practice. The following is the complete set of calculations with one set of assumptions, showing method of calculation:

Design of 5 K. W. Transformer.

The assumptions are:-

Current density - - 1,000 circular mils per ampere,

Number of turns on primary 132,

Diameter core 3-1/2",

Data as given for design:-

Capacity 5 K. W.,

Current in sec. 1,000 amp.

Voltage of primary 110 volts,

Frequency 60 cycles.

Primary Current (I_p)

$$I_p = \frac{E_p I_p}{E_p} = \frac{5,000}{110} = 45.5 \text{ amperes.}$$

Size wire of primary coil.

Since 1,000 circular mils / amperes are allowed in primary, and primary carries 45.5 amperes; circular mil area will be $45.5 \times 1,000 = 45,500$ circular mils. This is equivalent to about 2 # 6 B & S wires.

(2 x 26,250 = 52,500 circular mils) will therefore be used.

Diameter = .1620 + .02 (which is the thickness of insulation) = .1820, dia. of insulated wire.

Current in secondary is 1,000 amperes; then

1,000 x 1,000 = 1,000,000 circular mils, required for sec.
This equals 785400 square mils.

Since two secondary coils will be in parallel, we have

$$\frac{785,400}{2} = 392,700 \text{ square mils / amperes,}$$

corresponding to

$$2" \times 1/4" \text{ copper ribbon} = 500,000 \text{ sq. mils.}$$

We will use 2-1/8" ribbons in parallel.

$$1/4 \times 3 \times (.02 \times 3) = .81" \text{ depth of series winding.}$$

$$(.135 \times 2) \times 2 = 2.27" \text{ outside dia. of spool.}$$

Space occupied by primary coil:-

Since the primary should have the same thickness as the secondary, then

$$\frac{.81}{.1820} = 4+$$

Therefore we will have four layers.

Now the capacity of the transformer 5 K. W., divided
by 1,000 amp. secondary current, $\frac{5,000}{1,000} = 5$ volts in

secondary. The ratio of transformation is

$$\frac{110}{5} = 22$$




With 132 turns on the primary we have $\frac{132}{22} = 6$ turns on the secondary.

In regard to the spacing of the coils, the best arrangement to reduce leakage, is to interlace the primary and secondary coils. So we will arrange the coils in this order on each leg of the transformer p,s,p,s,p; which makes six primary coils and four secondary coils in all, on the two legs; 132 turns on primary, and 6 primary coils makes

$\frac{132}{6} = 22$ turns per coil. So we will have 22 turns of 2

#6 B & S, #30 D. C. wire, arranged as shown in accompanying sketch.



This is 44 turns in all, or 12 turns wide in widest part.

$12 \times .182" = 2.184"$ space necessary for wire of one coil;

$2.184 + (.155 \times 2) = 2.45"$;

$2.45" \times 3 = 7.35"$ width of primary coils on one leg;

$2.27" \times 2 = 4.54"$ " " secondary coils on one leg;

11.89" " " all coils on one leg;

Allowing .04" between each coil $= (.04 \times 5) = .2"$ for clearance;

Allowing for bringing out leads $\frac{1}{4} + \frac{1}{4} + 3 (.182) = 1.046"$.

Then total length over all coils is $11.89" + .2" + 1.046" =$

13. 136".

Average dia. primary coil is $3.5" + 1" = 4.5"$;

Then length of one pri. turn is $4.5\pi"$;

length of 132 turns is $\frac{132 \times 4.5 \pi}{12} = 155$ feet.

Then we know that the resistance of any wire or rod is $R = \frac{\rho l}{A}$
where

ρ = specific mil foot resistance of copper = 12;

l = length of wire in feet;

A = area of cross section of wire in circular mils.

Then the resistance of the primary coil is

$$\frac{12 \times 155}{52500} = .0354 \text{ ohms.}$$


In the same way the resistance of the secondary coil is

$$\frac{12 \times \left(\frac{6 \times \pi \times 4.5}{12} \right)}{1,270,000} = .000,067 \text{ ohms.}$$

Then the total $I^2 R$ loss in the transformer is

$$(45.5 \times .0354) + (1000 \times .000067) = 140 \text{ watts;}$$

$$\frac{140}{5,000} \times 100 = 2.8\% \text{ copper loss at full load.}$$



Net area of cross section of this iron is

7.8 sq. in., allowing 10% for insulation.

Length of each leg is 13.5" between the ends as shown in this sketch of iron core, which leaves about .4" for clearance at ends of coils. Then the volume of these legs is $7.8 \times 13.5 \times 2 = 211$ cu. in. ~~We have~~

To have an area at the ends equal to 7.8, allowing for chamfering champhering, it is necessary to make the width 3". Then the volume of the two ends is $2 \times 7.8 \times 10.5 = 149$ cu in. Total volume of iron is then - -

$$211 + 149 = 360 \text{ cu. in.}$$

The formula for the hysteresis loss is - -

$$H = V_i f \eta B_m^{1.6} \times 10^{-7}$$

$$H = \frac{360 \times 60 \times .002 \times 40,000^{1.6} \times 10^{-7}}{360 \times 60 \times .002 \times 23,100,000 \times 10^7} = 97.6 \text{ watts}$$

$$\frac{97.6 \times 100}{5,000} = 1.98\% \text{ iron loss}$$

The full load efficiency then is $100 - 2.8 - 1.98 = 95.4\%$ efficiency.

In the same manner we carried out the calculations with the above named assumptions. The results of the calculations are given in the following table. In the case where we assumed 88 turns on the primary coil it was found that the flux density was too high as is seen by the figures shown.

Data from calculations of 5 K. W. high current Transformer.

60 Cycles --		V_p	IIO --	V_s	5 --	$I_{45.45}$	--	I_s	--	I000	
Dia. "		No of turns:		A "	$V_{cu} = (I^2 R)$	$I^2 R$	Total	Iron	loss	Eff	Watts
		P	S								
3	I/4	132	6	5.6	230	65	59	2.50	2.01	95.49	54000
3	I/4	"	"	6.7	291	69	63	2.64	1.99	95.5	46700
3	I/2	"	"	7.8	360	73	67	2.80	2.00	95.4	40000
3	3/4	"	"	8.6	411	77	70	2.94	1.92	95.45	36600
4	"	"	"	9.9	474	81	74	3.10	1.71	95.4	31600
3	I/4	132	6	5.6	230	56.8	45.8	2.05	2.01	95.96	54000
3	I/4	"	"	6.7	291	60.4	48.6	2.13	1.99	95.83	46700
3	I/2	"	"	7.8	360	64.1	51.6	2.21	2.00	95.79	40000
3	3/4	"	"	8.6	411	67.5	54.2	2.43	1.92	95.65	36600
4	"	"	"	9.9	474	70.3	57.0	2.54	1.71	95.75	31600
3	I/4	132	6	5.6	230	51.4	39.4	1.82	2.01	96.17	54000
3	I/4	"	"	6.7	291	54.6	41.8	1.93	1.99	96.08	46700
3	I/2	"	"	7.8	360	57.8	44.4	2.02	2.00	95.98	40000
3	3/4	"	"	8.6	411	61.1	46.8	2.16	1.92	95.92	36600
4	"	"	"	9.9	474	64.0	49.0	2.18	1.81	96.01	31600
3	I/4	176	8	5.6	230	67	78	3.31	1.35	95.34	41800
3	I/4	"	"	6.7	291	92	84	3.52	1.30	95.13	35000
3	I/2	"	"	7.8	360	97	89	3.71	1.26	95.03	30000
3	3/4	"	"	8.6	411	103	93.5	3.93	1.18	94.89	27200
4	"	"	"	9.9	474	108	97	4.10	.97	94.93	23600
3	I/4	176	8	5.6	230	75.7	61.0	2.73	1.35	95.92	41800
3	I/4	"	"	6.7	291	80.5	64.9	2.91	1.30	95.79	35000
3	I/2	"	"	7.8	360	85.5	68.6	3.08	1.26	95.66	30000
3	3/4	"	"	8.6	411	90	72.4	3.25	1.18	95.57	27200
4	"	"	"	9.9	474	95	76.0	3.42	.97	95.61	23600
3	I/4	176	8	5.6	230	68.7	52.0	2.43	1.35		41800
3	I/4	"	"	6.7	291	72.8	52.8	2.57	1.30		35000
3	I/2	"	"	7.8	360	77.2	59.2	2.73	1.26		30000
3	3/4	"	"	8.6	411	81.5	62.5	2.88	1.18		27200
4	"	"	"	9.9	474	85.0	64.0	2.98	.97		23600

-II-

Dia. "		No of Turns		"	"	"	"	Total Iron		O mils.	
P	S	Area	Vol:	(1 ² R)	(1 ² B)	I R	loss	Eff	B/a	per atm	
3	:	88	:	5.6	230	:	:	:	:	83900	1000
3 1/4	:	"	:	6.7	291	:	:	:	:	70000	"
3 1/2	:	"	:	7.8	360	:	:	:	:	60000	"
3 3/4	:	"	:	8.6	411	:	:	:	:	54400	"
4	:	"	:	9.9	474	:	:	:	:	47200	"
3	:	88	:	5.6	230	37.1	30.5	1.35	4.35	83900	1300
3 1/4	:	"	:	6.7	291	40.4	33.3	1.45	:	70000	"
3 1/2	:	"	:	7.8	360	42.6	34.4	1.54	:	60000	"
3 3/4	:	"	:	8.6	411	45.1	36.2	1.62	:	54400	"
4	:	"	:	9.9	474	48.10	38.1	1.72	:	47200	"
3	:	88	:	5.6	230	34.4	26.3	1.2	:	83900	1500
3 1/4	:	"	:	6.7	291	36.7	27.9	1.39	:	70000	"
3 1/2	:	"	:	7.8	360	38.5	28.6	1.34	:	60000	"
3 3/4	:	"	:	8.6	411	40.3	31.2	1.43	:	54400	"
4	:	"	:	9.9	474	42.2	32.8	1.50	:	47200	"

Flux Density too high
 →

From these calculations we decided ^{to use} ~~the~~ the 3 1/2" core with 132 turns on the primary and six turns on the secondary and with a current density of 1500 circular mils per ampere.

It has been found by experience that for a transformer operating under full load conditions, the iron losses should be made practically equal to the copper losses for best results. The calculations made with the above chosen assumptions, giving the best efficiency, also answer these conditions.

The next thing we did was to obtain a test ring of laminated iron of the quality which we expect to use in the construction of the transformer, and insulated in the same manner. On this ring were wound a primary and a secondary coil.

We decided to first obtain a B - H. curve for the iron in this sample ring, in order to ascertain whether the quality was of a suitable grade to be used in the construction of the transformer core. In order to do this it was necessary to make use of a ballistic galvanometer, in the Ewing's Ring Method of Determining a B - H. curve.

Before using this galvanometer we found that it was necessary to accurately obtain its constant K, which constant represents the deflection, in millimeters, of the moving system of the galvanometer, upon the application of one coulomb of electricity, at its terminals.

The method used to determine this constant was to charge a standard one-third microfarad condenser at certain known voltages



and then discharge same through the galvanometer noting the resultant deflection

Then we have

$$Q = K \rho$$

$$\& Q = C E$$

Hence
$$K \rho = C E$$

$$K = \frac{C E}{\rho}$$

Where $Q =$ quantity in coulombs

$K =$ galvanometer constant

$C =$ capacity in farads

$E =$ E. M. F. in volts

$\rho =$ Deflection in mm

The results we obtained were as follows:-

Voltage	ρ in mm.	ρ per volt
1	72	72
2	152	76
3	217	72
4	270	75

Average ρ per volt = 74.

Substituting in above equation for K , we have $K = \frac{45 \times 10^{-6} \times 1}{74} =$

-10
45 X 10

Having obtained this constant we then proceeded to determine the B-H curve. To do this we send a known current through the primary coil, which gives a value of H . which can be calculated from the formula $H = \frac{4\pi n I}{10c}$, where

H = strength of field

n_p = number of turns on primary coil

I = current in amperes in " "

l = mean length of ring in cm

Then the flow of the current in the primary induces a current in the secondary which causes a deflection of the moving system of the galvanometer. From this we can calculate the value of B corresponding to this value of H , with the formula

$$B_m = \frac{10^8 R K \rho}{2 n_s A} \quad \text{in which}$$

B = flux density in lines / \square cm

R = resistance of galvanometer circuit

K = galvanometer constant

ρ = " deflection in mm

n = number of turns on secondary coil

A = area of cross section of iron ring in \square cm

This gives the maximum value of $B = B_m$ for the intermediate values of B , decrease the flux H . from the maximum to the point desired and no reversal is necessary.

In the case $B_1 = \frac{10^8 R K \rho}{n_s A}$ in which B_1 is the difference between the maximum flux and the flux for the point desired. Then to

obtain the flux for the point desired = B_2 , we have $B_2 = B - B_1$,

$$B = \frac{10^8 R K \rho}{n_s A}$$

Obtaining a number of values of B & H . in this manner, which are given below, we found upon plotting the accompanying $B. H.$ curve

for the sample, that we obtained a hysteresis loop of small area and as this area represents the amount of energy lost by hysteresis, per cycle, we can see that this is a very good quality of iron for the purpose.

The data and results of this test are as follows:-

Primary Coil = 220 turns $\frac{1}{16}$ I4 R & S

Secondary " = 660 " $\frac{1}{16}$ 22 " " "

Weight of iron = 9.907 $\frac{1}{16}$

Inside dia. ring = 10.5" = 26.67 cm

Outside " " = 12.5" = 31.78 cm

Area of cross section of ring = 6.37 $\frac{1}{16}$ cm

K = galvanometer constant = 45 X 10^{-10}


$$\text{Then Bm} = \frac{10^3 \text{ R K P}}{2 \pi_s A} = \frac{10^3 \times 780000 \times 45 \times 10^{-10} \times 372}{2 \times 660 \times 6.37} = 15.520$$


-16-

10 R.K.P.


B

I (amperes)	R (ohms)	$\rho = \text{def in mm}$	$\mu_s R$	H	lines / cm
0	200000	215	4610	0	I0910
.5		160	3425	1.565	I2095
1.0		84	1800	3.140	I3720
1.5		61	1307	4.71	I4113
2.0		51.5	1103	6.28	I4417
2.5		43.0	922	7.85	I4598
3.0		37.0	792	8.42	I4728
3.5		33.0	707	9.99	I4813
4.0		23.0	492	11.56	I5028
4.5		24.0	514	12.13	I5006
5.0		23.5	503	13.70	I5017
5.5		20.0	428	15.27	I5092
6.0		17.0	364	16.84	I5156
6.5		14.0	300	17.41	I5220
7.0		10.0	214	18.98	I5305
7.5	100000	20.0	214	20.55	I5306
8.0		15.5	166	23.69	I5354
8.5					
9.0		5.0	54	26.83	I5466
9.5					
10.0		0	0	30.07	I5520
-0	700000	61.5	4620	0	I0900
-.5		271	20800	1.565	5280
-1.0		343	25700	3.14	I0180
-1.5		368	27600	4.71	I2080
-2.0		383	28700	6.28	I3180
-2.5	780000	347	29000	7.85	I3480
-3.0		352	29400	8.42	I3880
3.5		360	30100	9.99	I4580
4.0		364	30400	11.56	I4800
4.5		365	30500	12.13	I4980
5.0		364.5	30450	13.70	I4980
5.5		368.0	30700	15.27	I5180
6.0		365.0	30500	16.84	I4980
7.0		366.5	30600	18.98	I5080
8.0		369.5	30900	23.69	I5380
9.0		371.0	31000	26.83	I5480
10.0		372.0	31040	30.07	I5520






B-H CURVE
AND
HYSTERESIS LOOP
FOR
SAMPLE IRON TEST RING



CALIBRATION CURVE
FOR
WATMETER #2298--

TRUE WATTS

WATMETER READING



After determining that the iron was of a good quality for use in the construction of the transformer, we next determined the iron loss of the sample of iron, by the open circuit secondary method; the scheme of which is as shown in accompanying sketch. We know that with the secondary circuit of any transformer open, the only current which flows in the primary circuit is the exciting i current, which is made up of two components at right angles; one the magnetizing current, which is the current required to magnetize the core of the transformer and which is 90° behind the impressed E. M. F. and therefor the wattless component. The other component of the exciting current, is that required to make up for the iron losses in the machine. This current is in phase with the E. M. F. and the product of the two multiplied by the power factor, will give the iron loss in watts and is the reading of the wattmeter in the accompanying scheme. The results of this determination are as follows:

	Wattmeter reading		corrected				
Volts	Watts loss		Watts loss	B/σ_{cm}	I	B/σ''	
10	2.3	:	2.3	: 2680	: .30	: 17300	
20	6.5	:	6.5	: 5360	: .40	: 34600	
25	9.5	:	9.6	: 6700	: .45	: 43800	
30	10.5	:	10.6	: 8240	: .50	: 53200	
40	14.7	:	14.8	: 10720	: .60	: 68000	
50	24.3	:	24.5	: 13400	: .75	: 86500	
60	33.7	:	34.0	: 16080	: 1.15	: 108200	

IRON LOSS CURVE
FOR
SAMPLE IRON TESTING, ---

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

61

62

63

64

65

66

67

68

69

70

71

72

73

74

75

76

77

78

79

80

81

82

83

84

85

86

87

88

89

90

91

92

93

94

95

96

97

98

99

100

101

102

103

104

105

106

107

108

109

110

111

112

113

114

115

116

117

118

119

120

121

122

123

124

125

126

127

128

129

130

131

132

133

134

135

136

137

138

139

140

141

142

143

144

145

146

147

148

149

150

151

152

153

154

155

156

157

158

159

160

161

162

163

164

165

166

167

168

169

170

171

172

173

174

175

176

177

178

179

180

181

182

183

184

185

186

187

188

189

190

191

192

193

194

195

196

197

198

199

200

201

202

203

204

205

206

207

208

209

210

211

212

213

214

215

216

217

218

219

220

221

222

223

224

225

226

227

228

229

230

231

232

233

234

235

236

237

238

239

240

241

242

243

244

245

246

247

248

249

250

251

252

253

254

255

256

257

258

259

260

261

262

263

264

265

266

267

268

269

270

271

272

273

274

275

276

277

278

279

280

281

282

283

284

285

286

287

288

289

290

291

292

293

294

295

296

297

298

We used the secondary, or coil with greater number of turns, as the primary coil, because more accurate results are obtained than would be if we had used the other coil.

By varying the excitation of the generator we obtained the voltages impressed on the ring transformer, given in the first column of the data and also the corresponding reading, of the exciting current and watts iron loss. The values of B. given are calculated with the formula $B = \frac{10^8 E}{\sqrt{2} \pi A f n \mu}$, obtained from the general formula for the transformer given in a former part of this thesis.

We obtained a calibration curve for the wattmeter, given on the accompanying page, from which we found the correct watts corresponding to the reading taken.

Now we know that the iron loss varies directly as the volume of iron. By calculation we found the net volume of iron of the transformer to be 360 cu. in. The volume of the iron test ring is 36.2 cu. in. By calculation the iron loss in the transformer was 2 % or 100 watts at a density of about 43000 lines per sq. in. From the iron loss curve for the ring, the iron loss at a density of 43000 lines per sq. in is 9.6 watts. As the volume of the ring is about 1/10 of the calculated volume of the transformer iron. $9.6 \times 10 = 96$ watts is the iron loss of the transformer as obtained in this manner, which agrees very closely with the calculated value.

As we expected to obtain the material for the construction

of the transformer from the Western Electric CO. of Chicago, we obtained a list of the sizes and styles of wire which they had in stock, from which we chose the sizes corresponding to the current densities and areas required for the coils of the transformer.

We finally settled upon the following, as the best suited for the construction of the transformer, taking into consideration both cost and time of delivery of goods to us.

Primary coils (current density 1500 O mils per ampere) 132 turns of # 2 square wire as shown in accompanying drawing. (We found later that we would have to change this to # 2 B. & S., # 60 Double Cotton covered round wire, as the cost of the former proved to be too great). We used six coils in series and 22 turns per coil.


Secondary coils - Current density 1500 square mils per ampere.

Six turns of # 9 B & S. copper ribbon, 2 - 1" wide and 3 wires in parallel, making 6 ribbons in all and 3 turns per coil.

Four coils to be connected either in series or in parallel. When connected in series, the secondary current is 500 amperes, and when connected in parallel the secondary current is 1000 amperes.


Assuming .015" as the thickness of the laminations, we found, by dividing the width of iron of each size by .015 the number of sheets of metal necessary for each part of the curve. For instance

PRIMARY CELL-6





SECONDARY COIL-4







A



7 1/8"

200 PIECES WITH $A = 1 \frac{1}{8}"$

92 " $A = 1 \frac{3}{8}"$

76 " $A = 1 \frac{5}{8}"$

60 " $A = 1 \frac{7}{8}"$

ALL ROLLED, ANNEALED AND PAINTED



1 1/8"





16 1/4"

200 PIECES WITH $A = 3 \frac{1}{8}"$
92 " $A = 3 \frac{3}{8}"$
76 " $A = 3 \frac{5}{8}"$
60 " $A = 3 \frac{7}{8}"$

ALL ROLLED, ANNEALED AND PAINTED

5 K. W. TRANSFORMER PUNCHINGS.




5 KW. TRANSFORMER 110 V. PRIMARY 5 OR 10 V. SEC.



in the accompanying sketch the pieces for each leg, that were to be $3 \frac{1}{8}$ " wide, would have to fill $1 \frac{1}{2}$ " in width on each leg, making 3" for both legs.

Then $\frac{3}{.015} = 200$ sheets of metal necessary as is seen on accompanying drawing.

No account of insulation was taken in this case, as we wished to have several extra ones on hand, in case any of them proved defective in any way.



The pieces are assembled as shown in the accompanying sketch, the laminations being changed with regard to the position of the joint a, a., so that the joint will not come

at the same place, with each lamination, as this would cause a sort of an air gap, which would require a higher exciting current and tend to decrease the efficiency of the transformer.

The transformer as it will appear when assembled is shown by the accompanying blue print.

The bottom and the two legs of the core are first assembled, the bottom being clamped together with the wood clamps as shown. Then on each leg is wrapped, pressboard $\frac{1}{8}$ " thick. The coils are placed on the outside of this, and then the upper part of the core is assembled and clamped as shown.





